

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
1594 West North Temple - Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801
Telephone: (801) 538-5291
Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

- 1. Report Time Period: From (mo./yr.) January 1 2005 To (mo./yr.) December 31 2005
- 2. DOGM File Number (Mine No): M /030 /004
- 3. Mine Name: Montello Mine
- 4. Mineral(s) Mined (or permitted to mine): Clay
- 5. Type of mine: Surface Mine or Underground Mine
- 6. Legal Description (Location of Lands Affected):
1/4, 1/4, 1/4, Section 7, Township 9N, Range 17W
1/4, 1/4, 1/4, Section 12, Township 9N, Range 18W
1/4, 1/4, 1/4, Section, Township, Range
- 7. Name of Operator or Company: Pabco Building Products LLC dba Interstate Brick
- 8. Permanent Street Address: 9780 South, 5200 West
City, State, Zip: West Jordan, Utah 84088
Phone: 801-280-5200 Fax: 801-280-5225
- 9. Company Representative (or designated operator):
Name: John Hewitt
Title: Assistant Plant Mgr.
Business Address: 9780 South 5200 West
City, State, Zip: West Jordan, UT 84088
Phone: 801-280-5230 Fax: 801-280-5245

Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

- 1. Was there any mine related activity during the past year? Yes No
- 2. If no - what was the last year of activity? _____
- 3. If yes - how much ore or mineral was mined? Approximately 20,000 tons

RECEIVED
JAN 31 2006 0001

4. Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.

Mined some material from the floor area of the mine at the foot of the highwall. Removed approximately 1 acrea of overburden from the top of the high wall in anticipation of blasting, mining and reducing the slope of the wall. The Blasting is anticipated to occur in 2006.

5. How much **additional acreage** was disturbed during the past year? Approx. 2 acres

6. How much acreage was **reclaimed** during the past year? none

7. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

none

8. What is the **total disturbed acreage of entire project** at years end? 11 acres.

9. Briefly summarize any mining and/or reclamation plans for the upcoming year.

none planned. Will mine again this year probably after blasting. Hope to mine approximately 20,000 tons.

NOTE: Section III., "Additional Information" applies only to **large mining operations**.

III. Additional Information - R647-4-121.2 and .3


1. **The operator shall include an updated map depicting surface disturbance and reclamation performed during the year**, prepared in accordance with Rule R647-4-105.
2. The operator shall keep and maintain timely records relating to his performance under the Act, and shall make these records available to the Division upon request.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): John Hewitt

Title of Operator: Assistant Plant Mgr.

Signature of Operator: 

Date: 1-31-06


Legend



disturbed through 2003 area 8.5 acres




haulroad 9 miles to Hwy. BLM right of way UTU-039326, Sections 12,14,23,26,27,34; 16.72 acres



area of overburden removal 2005 mining activity



approximate location of overburden stockpile 2005 mining activity



Interstate brick Montello Mine M/490/005
Map for MR-AR, 2005 Mining Activity
Rocky Pass Creek USGS topo Map
T9N, R17W, Section 7
November 20, 2005, JH